



Jonathan Gish, AIA
Principal Architect

Jeff Morris, AIA
Mike Clark, AIA
Associate Architects

Andrew Huff, PE, AIA
Structural Engineering

August 6, 2026

ADDENDUM #1

FOR
VON RENNER ELEMENTARY SCHOOL: CLASSROOM BUILDING

FOR
NEWMAN-CROWS LANDING UNIFIED SCHOOL DISTRICT
Bid Time and Date: August 26, 2026, at 3:00 p.m.

GENERAL

The following addendum to the Plans and Specifications shall amend and take precedence over the original contract drawings and specifications.

Item 1.: See attached Asbestos Sampling Report, dated 7/22/26, and Bulk Paint Sampling (Lead) Report, dated 7/22/26, for the portables in the scope of work.

END OF ADDENDUM

Mountain View Environmental
5412 Shelly Court Salida, Ca 95368
Office (209) 545-8753 Mobile (209) 484-4395

Asbestos, Lead Based Paint & Mold
Consulting, Inspections & Supervision
Specializing in CDBG funded programs
E-mail: mountainviewenvironmental@gmail.com

ASBESTOS SAMPLING REPORT

Von Renner Elementary School
1388 Patchett Drive
Newman, CA 95360



7/22/26

Mountain View Environmental
5412 Shelly Court Salida, Ca 95368
Office (209) 545-8753 Mobile (209) 484-4395

Asbestos, Lead Based Paint & Mold
Consulting, Inspections & Supervision
Specializing in CDBG funded programs
E-mail: mountainviewenvironmental@gmail.com

ASBESTOS SAMPLING REPORT

At the request of Matt Vargas, Director of Maintenance & Operations, Newman-Crows Landing Unified School District, on July 22, 2026, Ken Horrillo, Certified Asbestos Consultant, Mountain View Environmental performed a sampling of Suspected Asbestos Containing Building Material on the Von Renner Elementary School Project located at 1388 Patchett Drive Newman, CA 95360.

The purpose of the Asbestos Sampling Report is to confirm or deny the existence of asbestos in suspected building materials that will become impacted by the demolition and relocation of the Modular classrooms.

This is a requirement of the United States Environmental Protection Agency (EPA) and the National Emissions Standards for Hazardous Air Pollutants (NESHAP) 40 CFR and the San Joaquin Valley Unified Air Pollution Control District.

PROPERTY DESCRIPTION

The demolition and relocation project will be impacting the Von Renner Elementary School located at 1388 Patchett Drive Newman, CA 95360. These eight modular buildings serve as classrooms for the school.

SAMPLING

Sampling was performed following the sampling guidelines under AHERA. The samples were collected placed in their own individual containers, assigned a unique sampling number, placed under a chain-of-custody and delivered to EMSL Analytical Inc. 464 McCormick Street San Leandro, CA 94577 for analysis by Polarized Light Microscopy. EMSL, Inc. is an EPA certified laboratory.

Mountain View Environmental
5412 Shelly Court Salida, Ca 95368
Office (209) 545-8753 Mobile (209) 484-4395

Asbestos, Lead Based Paint & Mold
Consulting, Inspections & Supervision
Specializing in CDBG funded programs
E-mail: mountainviewenvironmental@gmail.com

SAMPLING AND LABORATORY RESULTS USING BULK SAMPLING

Suspected Building Material

A-1	Vinyl Sheet Flooring / Room #15 /White	No Asbestos Detected
A-1	Mastic / Room #15 / Brown	No Asbestos Detected
A-1	Compound / Room #15 / White	No Asbestos Detected
A-2	Baseboard / Room #15 / Blue	No Asbestos Detected
A-2	Mastic / Room #15 / White	No Asbestos Detected
A-3	Carpet / Room #15 Floor Tile / Floor / Blue / Gray	No Asbestos Detected
A-3	Mastic 1 / Room #15 / Tan	No Asbestos Detected
A-3	Mastic 2 / Room #15 Brown	No Asbestos Detected
A-3	Compound / Room #15 / White	No Asbestos Detected
A-4	Vinyl Sheet Paneling / Room #15 / Brown	No Asbestos Detected
A-5	Fiberboard Ceiling Panels / Room #15 / Beige	No Asbestos Detected
A-6	Styrofoam Ceiling Panels / Room #15 / White	No Asbestos Detected
A-7	Vinyl Sheet Paneling / Exterior siding Room #15 & 16 / Gray / Beige	No Asbestos Detected
A-7	Mastic / Exterior Siding Room #15 & 16 / Tan	No Asbestos Detected
A-8	Vinyl Sheet Paneling /Exterior Siding Room #15 & 16 / Gray / Tan	No Asbestos Detected
A-8	Mastic / Exterior Siding Room #15 & 16 / Beige	No Asbestos Detected
A-9	Vinyl Sheet flooring / Room # 16 / Brown / Gray	No Asbestos Detected
A-9	Mastic / Room #16 / Tan	No Asbestos Detected
A-10	Fiberboard Ceiling panels / Room #16 / Gray	No Asbestos Detected
A-11	Carpet / Room #16 / Gray / Blue	No Asbestos Detected
A-11	Mastic / Room #16 / Brown	No Asbestos Detected
A-12	Vinyl Wall Paneling / Room #16 / Brown / White	No Asbestos Detected
A-13	Baseboard / Room #16 / Blue	No Asbestos Detected
A-13	Mastic / Room # 16 / Tan	No Asbestos Detected
A-14	Baseboard / Room #17 / Beige	No Asbestos Detected
A-14	Mastic / Room #17 / Brown	No Asbestos Detected
A-15	Vinyl Wall Panels / Room #17 / Beige	No Asbestos Detected
A-16	Carpet / Room # 17 / Blue / Green	No Asbestos Detected
A-16	Mastic / Room #17 / Tan	No Asbestos Detected
A-17	Carpet / Room #18 / Blue / Green	No Asbestos Detected
A-17	Mastic / Room #18 / Tan	No Asbestos Detected
A-18	Baseboard / Room # 18 / Beige	No Asbestos Detected
A-18	Mastic / Room #18 / Brown	No Asbestos Detected
A-19	Vinyl Wall Paneling / Room #18 /Beige	No Asbestos Detected
A-20	Vinyl Sheet Paneling / Exterior Siding Rms #17 & #18 / Gray / White	No Asbestos Detected
A-20	Mastic / Exterior Siding Rooms #17 & #18 / Gray	No Asbestos Detected
A-21	Vinyl Sheet Paneling / Exterior Siding Rooms #17 &18 / Gray / White	No Asbestos Detected

Mountain View Environmental
5412 Shelly Court Salida, Ca 95368
Office (209) 545-8753 Mobile (209) 484-4395

Asbestos, Lead Based Paint & Mold
Consulting, Inspections & Supervision
Specializing in CDBG funded programs
E-mail: mountainviewenvironmental@gmail.com

A-21	Mastic / Exterior Siding Rooms #17 & #18 / Gray / White	No Asbestos Detected
A-22	Vinyl Wall Paneling / Room # 19 / Brown	No Asbestos Detected
A-22	Wrap Vinyl Wall Paneling / Room #19 / White Beige	No Asbestos Detected
A-23	Carpet / Room # 19 / Gray /Blue	No Asbestos Detected
A-23	Mastic / Room # 19 / Yellow	No Asbestos Detected
A-24	Fiberglass Ceiling Panels / Room # 19 / Yellow	No Asbestos Detected
A-25	Exterior Siding / Exterior Room # 19 / Tan	No Asbestos Detected
A-26	Exterior Siding / Exterior Room # 19 / Tan	No Asbestos Detected
A-27	Vinyl wall Paneling / Room # 20 / Brown	No Asbestos Detected
A-27	Vinyl wall Wrap / Room # 20 / White / Beige	No Asbestos Detected
A-28	Carpet / Room # 20 / Gray / Blue	No Asbestos Detected
A-28	Mastic / Room #20 / Yellow	No Asbestos Detected
A-29	Concrete/ Footing Room # 20 / Gray	No Asbestos Detected
A-30	Vinyl wall Paneling / Room # 21 / Brown / White	No Asbestos Detected
A-31	Carpet / Room # 21 / Orange	No Asbestos Detected
A-31	Mastic / Room # 21 / Brown	No Asbestos Detected
A-32	Baseboard / Room # 21 / Brown	No Asbestos Detected
A-32	Mastic / Room # 21 / Brown	No Asbestos Detected
A-33	Fiberboard Ceiling Panels / Room # 22 / Brown	No Asbestos Detected
A-34	Carpet / Room # 22 / Black / Blue	No Asbestos Detected
A-34	Mastic / Room # 22 / Tan	No Asbestos Detected
A-35	Vinyl Wall Panels / Room # 22 / Brown / White	No Asbestos Detected
A-36	Baseboard / Room # 23 / Gray	No Asbestos Detected
A-36	Mastic / Room # 23 / Beige	No Asbestos Detected
A-37	Vinyl Wall Panels / Room # 23 / Brown / White	No Asbestos Detected
A-38	Pad / Room # 23 / Beige	No Asbestos Detected
A-38	Mastic / Room #23 / Blue	No Asbestos Detected
A-39	Concrete Pad / Room #23 / Gray	No Asbestos Detected
A-40	Concrete Pad / Room # 24 / Gray	No Asbestos Detected
A-41	Carpet / Room # 24 / Gray / Black	No Asbestos Detected
A-41	Mastic / Room #24 / Tan / Clear	No Asbestos Detected
A-42	Baseboard / Room #24 / Blue	No Asbestos Detected
A-42	Mastic / Room #24 / White	No Asbestos Detected
A-43	Vinyl Sheet Flooring / Room #24 / White / Gray	No Asbestos Detected
A-43	Mastic / Room #24 / yellow	No Asbestos Detected
A-43	Leveler / Room #24 / Gray	No Asbestos Detected
A-44	Concrete Footing / Bldg. # 1 Room #15 & #15 / Gray	No Asbestos Detected
A-45	Foundation Skirting / Bldg. #2 Room #18 & #19 / Beige	No Asbestos Detected
A-46	Concrete Footing / Bldg. #2 Room #18 & #19 / Gray	No Asbestos Detected

Mountain View Environmental
5412 Shelly Court Salida, Ca 95368
Office (209) 545-8753 Mobile (209) 484-4395

Asbestos, Lead Based Paint & Mold
Consulting, Inspections & Supervision
Specializing in CDBG funded programs
E-mail: mountainviewenvironmental@gmail.com

A-47	Membrane / Bldg. #3 Room #15 & #16 / White	No Asbestos Detected
A-47	Roofing Mineral Cap / Bldg. #3 Room #15 & 16 / Black	No Asbestos Detected
A-47	Roofing Felt / Bldg. #3 Room #15 & 16 / Black	No Asbestos Detected
A-48	Roofing Membrane / Bldg. #3 Room #15 & #16 / White	No Asbestos Detected
A-48	Roofing Mineral Cap / Bldg. #3 Room #15 & #16 / Black	No Asbestos Detected
A-48	Felt/ Bldg. #3 Room #15 & #16 / Black	No Asbestos Detected
A-49	Roofing Membrane / Bldg. #2 Room #17 & #18 / White	No Asbestos Detected
A-49	Roofing Mineral Cap / Bldg. #2 Room #17 & #18 / Black	No Asbestos Detected
A-50	Roofing Membrane / Bldg. #2 Room #17 & #18 / White	No Asbestos Detected
A-50	Roofing Mineral Cap / Bldg. #2 Room #17 & #18 / Black	No Asbestos Detected
A-51	Roofing Membrane / Bldg. #1 Room #19 / White	No Asbestos Detected
A-51	Roofing / Bldg. #1 Room #19 / Black	2% Chrysotile Detected
A-51	Roofing Mineral Cap / Bldg. #1 Room #19 / Brown Gray Black	30% Chrysotile Detected
A-52	Roofing Membrane / Bldg. #1 Room #19 / White	No Asbestos Detected
A-52	Roofing / Bldg. #1 Room #19 / Black	2% Chrysotile Detected
A-53	Roofing Membrane / Bldg. #4 Room #23 / White	No Asbestos Detected
A-53	Roofing Mineral Cap / Bldg. #4 Room #23 / Gray Black	No Asbestos Detected
A-53	Felt / Bldg. #4 Room #23 / Black	No Asbestos Detected
A-54	Roofing Membrane / Bldg. #4 Room #23 / White	No Asbestos Detected
A-54	Roofing Mineral Cap/ Bldg. #4 Room #23 / Gray / Black	No Asbestos Detected
A-54	Felt / Bldg. #4 Room #23 / Black	No Asbestos Detected
A-55	Membrane / Bldg. #3 Room #22 / White	No Asbestos Detected
A-55	Roofing Mineral Cap / Bldg. #3 Room #22 / Gray / Black	No Asbestos Detected
A-55	Felt / Bldg. #3 Room #22 / Black	No Asbestos Detected
A-56	Roofing Membrane / Bldg. #3 Room #22 / White	No Asbestos Detected
A-56	Roofing Mineral Cap / Bldg. #3 Room #22 / Gray / Black	No Asbestos Detected
A-56	Felt / Bldg. #3 Room #22 / Black	No Asbestos Detected
A-57	Roofing Membrane / Bldg. #2 Room #21 / White	No Asbestos Detected
A-57	Roofing / Bldg. #2 Room #21 / Gray Black	No Asbestos Detected
A-58	Roofing Membrane / Bldg. #2 Room #21 /White	No Asbestos Detected
A-58	Roofing / Bldg. #2 Room #21 / Gray Black	No Asbestos Detected
A-59	Roofing / Bldg. #1 Room #20 / Gray Black	No Asbestos Detected
A-60	Roofing Mineral Cap / Bldg. #1 Room #20 / Gray Black	No Asbestos Detected
A-60	Felt / Bldg. #1 Room #20 / Black	No Asbestos Detected

Mountain View Environmental
5412 Shelly Court Salida, Ca 95368
Office (209) 545-8753 Mobile (209) 484-4395

Asbestos, Lead Based Paint & Mold
Consulting, Inspections & Supervision
Specializing in CDBG funded programs
E-mail: mountainviewenvironmental@gmail.com

SUMMARY

Samples A-51 and A-52 of the following suspected Asbestos containing building material that could be impacted by the by the demolition of the structure was shown by the laboratory analysis to contain more than 1 percent (1%) asbestos as determined by Polarized Light Microscopy (PLM) by an accredited laboratory.

The above-mentioned suspected building material identified at the site contains < 1% amount of Asbestos and is a regulated material per EPA/San Joaquin Valley Unified Air Quality District.

This material is considered Regulated Asbestos Containing Material (RACM) and does need to be handled and disposed of using EPA regulations.

Cal OSHA regulations do recognize any detectable amount of "Asbestos Containing Construction Material" in regards to worker safety. Worker safety is a concern; therefore, if this material is impacted or removed, it is required that the work be performed by a DOSH Certified Contractor.

It is a requirement of the San Joaquin Valley Unified Air Pollution Control district that all regulated asbestos containing materials that will be impacted must be removed and disposed of by a properly licensed California abatement contractor prior to the demolition or renovation of the building following all applicable laws and regulations pertaining to the removal and disposal of asbestos containing building materials.

See attachments:

- A- Chain of Custody
- B- Laboratory Asbestos Analysis for bulk Material
- C- Sampling location footprint



Ken Horrillo
CAC # 10-4691
Mountain View Environmental

EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Asbestos Chain of Custody For California

EMSL Order Number (lab use only):

#092608343

PHONE:
FAX:

Company Name : Mountain View Environmental		EMSL Customer ID:	
Street: 5412 Shelly Court		City: Salida	State or Province: CA
Zip/Postal Code: 95368	Country: US	Telephone #: 209-545-8753	Fax #:
Report To (Name): Ken Horrillo		Please Provide Results via: ☐ Fax ☒ Email	
email Address: Mountainviewenvironmental@gmail.com		Purchase Order Number:	
Client Project ID: 1388 Patchett Drive Newman, CA		EMSL Project ID (internal use only):	
State or Province Collected: CA			
EMSL Bill-to: ☒ Same ☐ Different: If Bill-to is different, note instructions in comments below. <i>Third-party billing requires written authorization.</i>			
Turnaround Time (TAT) Options Please Check			
☐ 3 Hr ¹	☐ 4-4.5Hr ¹ AHERA Only	☐ 6 Hr ¹	☐ 24 Hr
		☐ 32 Hr ²	☒ 48 Hr
		☐ 72 Hr	☐ 96 Hr
		☐ 1 Week	☐ 2 Week
¹Premium Service Charge applies for 3 Hour TEM AHERA or EPA Level II TAT – you will be asked to sign an authorization form. TEM Air 3 -6 Hour, please call ahead to schedule ²32 Hour TAT available for select tests only; samples must be submitted by 11.30am			
PCM – Air ☐ NIOSH 7400 ☐ w/ OSHA 8hr. TWA PLM – Bulk (Reporting Limit) ☒ PLM EPA 600/R-93/116 (<1%) ☐ PLM EPA NOB (<1%) ☐ 400 Point Count (<0.25%) ☐ 400 Point Count with Gravimetric Reduction (<0.25%) ☐ 1000 Point Count (<0.1%) ☐ 1000 Point Count with Gravimetric Reduction (<0.1%) ☐ NIOSH 9002 (<1%) TEM – Water: EPA 100.2 Fibers >10µm ☐ Waste ☐ Drinking All Fiber Sizes ☐ Waste ☐ Drinking		TEM – Air ☐ AHERA 40 CFR, Part 763 ☐ CARB Modified AHERA ☐ EPA Level II ☐ NIOSH 7402 ☐ ISO 10312 TEM – Bulk ☐ TEM EPA NOB ☐ TEM EPA 600/R-93/116 with Milling Prep (<0.1%)* Soil/Rock/Vermiculite (Reporting Limit) ☐ PLM CARB 435 – A (<0.25%)* ☐ TEM CARB 435 – B (<0.1%) ☐ TEM CARB 435 – C (<0.01%)* ☐ TEM Qualitative via Filtration Prep ☐ TEM Qualitative via Drop Mount Prep ☐ PLM EPA 600/R-93/116 with Milling Prep (<0.25%) ☐ PLM EPA 600/R-93/116 with Milling Prep (<0.1%) ☐ TEM EPA 600/R-93/116 with Milling Prep (<0.1%)* <i>* Lower reporting limits available upon request</i>	
TEM – Dust ☐ Microvac - ASTM D 5755 ☐ Wipe - ASTM D6480 ☐ Carpet Sonication (EPA 600/J-93/167)		Other test (please specify)	
☐ Stop At First Positive (clearly identify homogenous areas below)		Filter Pore Size (Air Samples): ☐ 0.8µm ☐ 0.45µm	
Sampler's Name: Ken Horrillo		Sampler's Signature: <i>Ken Horrillo</i>	
Sample #	Sample Description/ Location	Volume, Area, or Homogenous Area	Date and Time Sampled
A-1	Sheet vinyl goods -Entry - Room #15	Bulk	7-22-26/10:30am
A-2	Rubber Baseboard - Room #15	Bulk	7-22-26/10:30am
A-3	Carpet and mastic - Room #15	Bulk	7-22-26/10:30am
A-4	Vinyl wall panels - Room #15	Bulk	7-22-26/10:30am
Client Sample # (s): A-1 - A-60		Total # of Samples: 60	
Relinquished by (Client): Kenneth Horrillo		Date: 7-25-26	Time: 9:30
Received by (Lab): <i>James M. Fife</i>		Date: 7/28/26	Time: 8:45 AM
Comments/Special Instructions:			

Controlled Document – COC-51 Asbestos CA R1 09/03/2019

EMSL Analytical, Inc.'s (DBA: LA Testing) Laboratory Terms and Conditions are incorporated into this chain of custody by reference in their entirety. Submission of samples to LA Testing constitutes acceptance and acknowledgment of all terms and conditions.

Page 1 of 4 pages

Attachment A

Page 1 Of 4



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Chain of Custody For California

EMSL Order Number (Lab Use Only):

#092608343

PHONE:

FAX:

Additional Pages of the Chain of Custody are only necessary if needed
for additional sample information

Sample #	Sample Description/ Location	Volume, Area, or Homogenous Area #	Date and Time Sampled
A-5	Fiberboard ceiling Panels- Room #15	Bulk	7-22-10:30am
A-6	Styrofoam ceiling insulation- Room #15	Bulk	7-22-26/10:30am
A-7	Exterior siding- Room #15 & #16	Bulk	7-22-26/10:30am
A-8	Exterior siding - Room #15 & 16	Bulk	7-22-26/10:30am
A-9	Sheet vinyl goods -Entry - Room #16	Bulk	7-22-26/10:30am
A-10	Fiberboard ceiling Panels- Room #16	Bulk	7-22-26/10:30am
A-11	Carpet & Mastic - Room #16	Bulk	7-22-26/10:30am
A-12	Vinyl wall panels - Room #16	Bulk	7-22-26/10:30am
A-13	Baseboard & Mastic - Room #16	Bulk	7-22-26/10:30am
A-14	Baseboard & Mastic - Room #17	Bulk	7-22-26/10:30am
A-15	Vinyl wall panels - Room #17	Bulk	7-22-26/10:30am
A-16	Carpet and Mastic - Room #17	Bulk	7-22-26/10:30am
A-17	Carpet and mastic - Room #18	Bulk	7-22-26/10:30am
A-18	Baseboard & mastic - Room 18	Bulk	7-22-26/10:30am
A-19	Vinyl wall panels - Room #18	Bulk	7-22-26/10:30am
A-20	Exterior siding- Room #17 & #18	Bulk	7-22-26/10:30am
A-21	Exterior siding- Room #17 & #18	Bulk	7-22-26/10:30am
A-22	Vinyl wall panels - Room # 19	Bulk	7-22-26/10:30am
A-23	Carpet and Mastic -Room # 19	Bulk	7-22-26/10:30am
A-24	Fiberglass ceiling Panels- Room #19	Bulk	7-22-26/10:30am
A-25	Exterior siding- Room #19	Bulk	7-22-26/10:30am
A-26	Exterior siding- Room #19	Bulk	7-22-26/10:30am

*Comments/Special Instructions:

rec'd by CFA 7/28/20 8:45 AM

Page 2 of 4 pages

Controlled Document - COC-51 Asbestos CA R1 09/03/2019

EMSL Analytical, Inc.'s (DBA: LA Testing) Laboratory Terms and Conditions are incorporated into this chain of custody by reference in their entirety. Submission of samples to LA Testing constitutes acceptance and acknowledgment of all terms and conditions.

Attachment A

Page 2 Of 4



EMSL ANALYTICAL, INC.
LABORATORY • PRODUCTS • TRAINING

Asbestos Chain of Custody For California

EMSL Order Number (Lab Use Only):

#092608343

PHONE:

FAX:

Additional Pages of the Chain of Custody are only necessary if needed
for additional sample information

Sample #	Sample Description/ Location	Volume, Area, or Homogenous Area #	Date and Time Sampled
A-27	Vinyl wall panels - Room #20	Bulk	7-22-26/10:30am
A-28	Carpet & Mastic - Room #20	Bulk	7-22-26/10:30am
A-29	Concrete footing - Room #20	Bulk	7-22-26/10:30am
A-30	Vinyl wall panels - Room #21	Bulk	7-22-26/10:30am
A-31	Carpet & Mastic - Room #21	Bulk	7-22-26/10:30am
A-32	Baseboard & Mastic - Room #21	Bulk	7-22-26/10:30am
A-33	Fiberboard ceiling Panels- Room #22	Bulk	7-22-26/10:30am
A-34	Carpet & mastic - Room #22	Bulk	7-22-26/10:30am
A-35	Vinyl wall panels - Room #22	Bulk	7-22-26/10:30am
A-36	Baseboard & Mastic - Room #23	Bulk	7-22-26/10:30am
A-37	Vinyl wall panels - Room #23	Bulk	7-22-26/10:30am
A-38	Carpet Pad and Mastic - Room #23	Bulk	7-22-26/10:30am
A-39	Concrete footing - Room #23	Bulk	7-22-26/10:30am
A-40	Concrete Pad - Room #24	Bulk	7-22-26/10:30am
A-41	Carpet and Mastic - Room #24	Bulk	7-22-26/10:30am
A-42	Baseboard & Mastic- Room #24	Bulk	7-22-26/10:30am
A-43	Sheet vinyl goods -Entry - Room #24	Bulk	7-22-26/10:30am
A-44	Concrete footing - Rooms # 15 & 16 Bldg. #1	Bulk	7-22-26/10:30am
A-45	Foundation skirting - Rooms 18 & 19 Bldg. #2	Bulk	7-22-26/10:30am
A-46	Concrete footing- 18 & 19 Bldg. #2	Bulk	7-22-26/10:30am
A-47	Roofing Bldg. #3 - Room #15 & #16	Bulk	7-22-26/10:30am
A-48	Roofing Bldg. #3 - Room #15 & #16	Bulk	7-22-26/10:30am

*Comments/Special Instructions:

Page 3 of 4 pages

Controlled Document - COC-51 - Asbestos CA R1 09/03/2019

EMSL Analytical, Inc.'s (DBA: LA Testing) Laboratory Terms and Conditions are incorporated into this chain of custody by reference in their entirety. Submission of samples to LA Testing constitutes acceptance and acknowledgment of all terms and conditions.

Attachment A

Page 3 of 4

EMSL Order Number *(Lab Use Only):*

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

[illegible]

***Comments/Special Instructions:**

Rec: ~~J~~ ~~m~~ EFF ① 7/28/26 8:45a

Page 4 of 4 pages

Controlled Document – COC-51 Asbestos CA R1 09/03/2019

EMSL Analytical, Inc.'s (DBA: LA Testing) Laboratory Terms and Conditions are incorporated into this chain of custody by reference in their entirety. Submission of samples to LA Testing constitutes acceptance and acknowledgment of all terms and conditions

Attachment A

Page 4 of 4



EMSL Analytical, Inc.

464 McCormick Street San Leandro, CA 94577

Tel/Fax: (510) 895-3675 / (510) 895-3680

<http://www.EMSL.com> / sanleandrolab@emsl.com

EMSL Order: 092608343

Customer ID: 32MOUN22

Customer PO:

Project ID:

Attention: Results

Mountain View Environmental
5412 Shelly Court
Salida, CA 95368

Phone: (209) 545-8753

Fax: (209) 545-8753

Received Date: 07/28/2026 8:45 AM

Analysis Date: 07/30/2026 - 07/31/2026

Collected Date: 07/22/2026

Project: 1388 PATCHETT DRIVE NEWMAN, CA

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-1-Vinyl Sheet Flooring <i>092608343-0001</i>	SHEET VINYL GOODS - ENTRY - ROOM #15	White Fibrous Homogeneous	30% Cellulose	50% Matrix 20% Non-fibrous (Other)	None Detected
A-1-Mastic <i>092608343-0001A</i>	SHEET VINYL GOODS - ENTRY - ROOM #15	Brown Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-1-Compound <i>092608343-0001B</i>	SHEET VINYL GOODS - ENTRY - ROOM #15	White Non-Fibrous Homogeneous		30% Ca Carbonate 50% Gypsum 20% Non-fibrous (Other)	None Detected
A-2-Baseboard <i>092608343-0002</i>	RUBBER BASEBOARD - ROOM #15	Blue Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-2-Mastic <i>092608343-0002A</i>	RUBBER BASEBOARD - ROOM #15	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-3-Carpet <i>092608343-0003</i>	CARPET AND MASTIC - ROOM #15	Gray/Blue Fibrous Homogeneous	80% Synthetic	20% Non-fibrous (Other)	None Detected
A-3-Mastic 1 <i>092608343-0003A</i>	CARPET AND MASTIC - ROOM #15	Tan Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-3-Mastic 2 <i>092608343-0003B</i>	CARPET AND MASTIC - ROOM #15	Brown Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-3-Compound <i>092608343-0003C</i>	CARPET AND MASTIC - ROOM #15	White Non-Fibrous Homogeneous		70% Ca Carbonate 30% Non-fibrous (Other)	None Detected
A-4 <i>092608343-0004</i>	VINYL WALL PANELS - ROOM #15	Brown Fibrous Homogeneous	40% Cellulose 20% Synthetic	20% Matrix 20% Non-fibrous (Other)	None Detected
A-5 <i>092608343-0005</i>	FIBERBOARD CEILING PANELS - ROOM #15	Beige Fibrous Homogeneous	40% Cellulose 40% Min. Wool	20% Non-fibrous (Other)	None Detected
A-6 <i>092608343-0006</i>	STYROFOAM CEILING INSULATION - ROOM #15	White Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
A-7-Vinyl Sheet Paneling <i>092608343-0007</i> <i>This is a composite result of both vinyl and backing layer</i>	EXTERIOR SIDING - ROOM #15 AND 16	Gray/Beige Fibrous Homogeneous	40% Glass	40% Matrix 20% Non-fibrous (Other)	None Detected
A-7-Mastic <i>092608343-0007A</i>	EXTERIOR SIDING - ROOM #15 AND 16	Tan Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-8-Vinyl Sheet Paneling <i>092608343-0008</i>	EXTERIOR SIDING - ROOM #15 AND 16	Gray/Tan Fibrous Homogeneous	40% Glass	40% Matrix 20% Non-fibrous (Other)	None Detected

Report amended: 08/03/2026 16:08:37 Replaces initial report from: 07/31/2026 10:56:26 Reason Code: Client-Change to Sample ID



EMSL Analytical, Inc.

464 McCormick Street San Leandro, CA 94577

Tel/Fax: (510) 895-3675 / (510) 895-3680

<http://www.EMSL.com> / sanleandrolab@emsl.com

EMSL Order: 092608343

Customer ID: 32MOUN22

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

			Non-Asbestos	Asbestos	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
This is a composite result of both vinyl and backing layer					
A-8-Mastic 092608343-0008A	EXTERIOR SIDING - ROOM #15 AND 16	Beige Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-9-Vinyl Sheet Flooring 092608343-0009	SHEET VINYL GOODS - ENTRY - ROOM #16	Brown/Gray Fibrous Homogeneous	40% Cellulose	40% Matrix 20% Non-fibrous (Other)	None Detected
This is a composite result of both vinyl and backing layer					
A-9-Mastic 092608343-0009A	SHEET VINYL GOODS - ENTRY - ROOM #16	Tan Non-Fibrous Homogeneous		70% Matrix 30% Non-fibrous (Other)	None Detected
A-10 092608343-0010	FIBERBOARD CEILING PANELS - ROOM #16	Gray Fibrous Homogeneous	40% Cellulose 40% Min. Wool	20% Non-fibrous (Other)	None Detected
A-11-Carpet 092608343-0011	CARPET & MASTIC - ROOM #16	Gray/Blue Fibrous Homogeneous	80% Synthetic	20% Non-fibrous (Other)	None Detected
A-11-Mastic 092608343-0011A	CARPET & MASTIC - ROOM #16	Brown Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-12 092608343-0012	VINYL WALL PANELS - ROOM #16	Brown/White Fibrous Homogeneous	40% Cellulose 20% Synthetic	20% Matrix 20% Non-fibrous (Other)	None Detected
This is a composite result of both vinyl and backing layer					
A-13-Baseboard 092608343-0013	BASEBOARD & MASTIC - ROOM #16	Blue Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-13-Mastic 092608343-0013A	BASEBOARD & MASTIC - ROOM #16	Tan Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-14-Baseboard 092608343-0014	BASEBOARD & MASTIC - ROOM #17	Beige Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-14-Mastic 092608343-0014A	BASEBOARD & MASTIC - ROOM #17	Brown Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-15 092608343-0015	VINYL WALL PANELS - ROOM #17	Beige Fibrous Homogeneous	20% Cellulose	60% Matrix 20% Non-fibrous (Other)	None Detected
A-16-Carpet 092608343-0016	CARPET & MASTIC - ROOM #17	Blue/Green Fibrous Homogeneous	80% Synthetic	20% Non-fibrous (Other)	None Detected
A-16-Mastic 092608343-0016A	CARPET & MASTIC - ROOM #17	Tan Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-17-Carpet 092608343-0017	CARPET & MASTIC - ROOM #18	Blue/Green Fibrous Homogeneous	80% Synthetic	20% Non-fibrous (Other)	None Detected
A-17-Mastic 092608343-0017A	CARPET & MASTIC - ROOM #18	Tan Non-Fibrous Homogeneous		60% Matrix 40% Non-fibrous (Other)	None Detected
Result includes a small amount of inseparable attached material					
A-18-Baseboard 092608343-0018	BASEBOARD & MASTIC - ROOM #18	Beige Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected

Report amended: 08/03/2026 16:08:37 Replaces initial report from: 07/31/2026 10:56:26 Reason Code: Client-Change to Sample ID



EMSL Analytical, Inc.

464 McCormick Street San Leandro, CA 94577

Tel/Fax: (510) 895-3675 / (510) 895-3680

<http://www.EMSL.com> / sanleandrolab@emsl.com

EMSL Order: 092608343

Customer ID: 32MOUN22

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-18-Mastic <i>092608343-0018A</i>	BASEBOARD & MASTIC - ROOM #18	Brown Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-19 <i>092608343-0019</i>	VINYL WALL PANELS - ROOM #18	Beige Fibrous Homogeneous	20% Cellulose	60% Matrix 20% Non-fibrous (Other)	None Detected
A-20-Vinyl Sheet Paneling <i>092608343-0020</i>	EXTERIOR SIDING - ROOM #17 & #18	Gray/White Fibrous Homogeneous	40% Glass	40% Matrix 20% Non-fibrous (Other)	None Detected
A-20-Mastic <i>092608343-0020A</i>	EXTERIOR SIDING - ROOM #17 & #18	Gray Non-Fibrous Homogeneous	10% Glass	70% Matrix 20% Non-fibrous (Other)	None Detected
A-21-Vinyl Sheet Paneling <i>092608343-0021</i>	EXTERIOR SIDING - ROOM #17 & #18	Gray/White Fibrous Homogeneous	40% Glass	40% Matrix 20% Non-fibrous (Other)	None Detected
A-21-Mastic <i>092608343-0021A</i>	EXTERIOR SIDING - ROOM #17 & #18	Gray/White Non-Fibrous Homogeneous	10% Glass	70% Matrix 20% Non-fibrous (Other)	None Detected
A-22-Paneling <i>092608343-0022</i>	VINYL WALL PANELS - ROOM #19	Brown Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
A-22-Wrap <i>092608343-0022A</i>	VINYL WALL PANELS - ROOM #19	White/Beige Fibrous Homogeneous	40% Cellulose	40% Matrix 20% Non-fibrous (Other)	None Detected
A-23-Carpet <i>092608343-0023</i>	CARPET AND MASTIC - ROOM #19	Gray/Blue Fibrous Homogeneous	80% Synthetic	20% Non-fibrous (Other)	None Detected
A-23-Mastic <i>092608343-0023A</i>	CARPET AND MASTIC - ROOM #19	Yellow Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-24 <i>092608343-0024</i>	FIBERGLASS CEILING PANELS - ROOM #19	Yellow Fibrous Homogeneous	80% Min. Wool	20% Non-fibrous (Other)	None Detected
A-25 <i>092608343-0025</i>	EXTERIOR SIDING - ROOM #19	Tan Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
A-26 <i>092608343-0026</i>	EXTERIOR SIDING - ROOM #19	Tan Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
A-27-Paneling <i>092608343-0027</i>	VINYL WALL PANELS - ROOM #20	Brown Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
A-27-Wrap <i>092608343-0027A</i>	VINYL WALL PANELS - ROOM #20	White/Beige Fibrous Homogeneous	40% Cellulose	40% Matrix 20% Non-fibrous (Other)	None Detected
A-28-Carpet <i>092608343-0028</i>	CARPET & MASTIC - ROOM #20	Gray/Blue Fibrous Homogeneous	80% Synthetic	20% Non-fibrous (Other)	None Detected
A-28-Mastic <i>092608343-0028A</i>	CARPET & MASTIC - ROOM #20	Yellow Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-29 <i>092608343-0029</i>	CONCRETE FOOTING - ROOM #20	Gray Non-Fibrous Homogeneous		40% Quartz 40% Ca Carbonate 20% Non-fibrous (Other)	None Detected

Report amended: 08/03/2026 16:08:37 Replaces initial report from: 07/31/2026 10:56:26 Reason Code: Client-Change to Sample ID



EMSL Analytical, Inc.

464 McCormick Street San Leandro, CA 94577

Tel/Fax: (510) 895-3675 / (510) 895-3680

<http://www.EMSL.com> / sanleandrolab@emsl.com

EMSL Order: 092608343

Customer ID: 32MOUN22

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-30 <i>092608343-0030</i> <i>This is a composite result of both vinyl and backing layer</i>	VINYL WALL PANELS - ROOM #21	Brown/White Fibrous Homogeneous	50% Cellulose	30% Matrix 20% Non-fibrous (Other)	None Detected
A-31-Carpet <i>092608343-0031</i>	CARPET & MASTIC - ROOM #21	Orange Fibrous Homogeneous	80% Synthetic	20% Non-fibrous (Other)	None Detected
A-31-Mastic <i>092608343-0031A</i>	CARPET & MASTIC - ROOM #21	Brown Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-32-Baseboard <i>092608343-0032</i>	BASEBOARD & MASTIC - ROOM #21	Brown Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-32-Mastic <i>092608343-0032A</i>	BASEBOARD & MASTIC - ROOM #21	Brown Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-33 <i>092608343-0033</i>	FIBERBOARD CEILING PANELS - ROOM #22	Brown Fibrous Homogeneous	80% Cellulose	20% Non-fibrous (Other)	None Detected
A-34-Carpet <i>092608343-0034</i>	CARPET & MASTIC - ROOM #22	Black/Blue Fibrous Homogeneous	80% Synthetic	20% Non-fibrous (Other)	None Detected
A-34-Mastic <i>092608343-0034A</i>	CARPET & MASTIC - ROOM #22	Tan Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-35 <i>092608343-0035</i>	VINYL WALL PANELS - ROOM #22	Brown/White Fibrous Homogeneous	40% Cellulose	30% Matrix 30% Non-fibrous (Other)	None Detected
A-36-Baseboard <i>092608343-0036</i>	BASEBOARD & MASTIC - ROOM #23	Gray Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-36-Mastic <i>092608343-0036A</i>	BASEBOARD & MASTIC - ROOM #23	Beige Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-37 <i>092608343-0037</i>	VINYL WALL PANELS - ROOM #23	Brown/White Fibrous Homogeneous	50% Cellulose	30% Matrix 20% Non-fibrous (Other)	None Detected
A-38-Pad <i>092608343-0038</i>	CARPET PAD AND MASTIC - ROOM #23	Beige Fibrous Homogeneous	50% Synthetic	30% Matrix 20% Non-fibrous (Other)	None Detected
A-38-Mastic <i>092608343-0038A</i>	CARPET PAD AND MASTIC - ROOM #23	Blue Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-39 <i>092608343-0039</i>	CONCRETE FOOTING - ROOM #23	Gray Non-Fibrous Homogeneous		40% Quartz 40% Ca Carbonate 20% Non-fibrous (Other)	None Detected
A-40 <i>092608343-0040</i>	CONCRETE PAD - ROOM #24	Gray Non-Fibrous Homogeneous		40% Quartz 40% Ca Carbonate 20% Non-fibrous (Other)	None Detected
A-41-Carpet <i>092608343-0041</i>	CARPET AND MASTIC - ROOM #24	Gray/Black Fibrous Homogeneous	80% Synthetic	20% Non-fibrous (Other)	None Detected
A-41-Mastic <i>092608343-0041A</i>	CARPET AND MASTIC - ROOM #24	Tan/Clear Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-42-Baseboard <i>092608343-0042</i>	BASEBOARD & MASTIC - ROOM #24	Blue Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected

Report amended: 08/03/2026 16:08:37 Replaces initial report from: 07/31/2026 10:56:26 Reason Code: Client-Change to Sample ID



EMSL Analytical, Inc.

464 McCormick Street San Leandro, CA 94577

Tel/Fax: (510) 895-3675 / (510) 895-3680

<http://www.EMSL.com> / sanleandrolab@emsl.com

EMSL Order: 092608343

Customer ID: 32MOUN22

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-42-Mastic <i>092608343-0042A</i>	BASEBOARD & MASTIC - ROOM #24	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-43-Vinyl Sheet Flooring <i>092608343-0043</i> <i>This is a composite result of both vinyl and backing layer</i>	SHEET VINYL GOODS - ENTRY - ROOM #24	Gray/White Fibrous Homogeneous	10% Synthetic 5% Glass	60% Matrix 25% Non-fibrous (Other)	None Detected
A-43-Mastic <i>092608343-0043A</i>	SHEET VINYL GOODS - ENTRY - ROOM #24	Yellow Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-43-Leveler <i>092608343-0043B</i>	SHEET VINYL GOODS - ENTRY - ROOM #24	Gray Non-Fibrous Homogeneous		80% Ca Carbonate 20% Non-fibrous (Other)	None Detected
A-44 <i>092608343-0044</i>	CONCRETE FOOTING- ROOMS #15 & 16 BLDG #1	Gray Non-Fibrous Homogeneous		40% Quartz 40% Ca Carbonate 20% Non-fibrous (Other)	None Detected
A-45 <i>092608343-0045</i>	FOUNDATION SKIRTING - ROOMS18 & 19 BLDG #2	Beige Non-Fibrous Homogeneous		10% Quartz 70% Ca Carbonate 20% Non-fibrous (Other)	None Detected
A-46 <i>092608343-0046</i>	CONCRETE FOOTING - 18 & 19 BLDG. #2	Gray Non-Fibrous Homogeneous		40% Quartz 40% Ca Carbonate 20% Non-fibrous (Other)	None Detected
A-47-Membrane <i>092608343-0047</i>	ROOFING BLDG, #3 - ROOM #15 & #16	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-47-Shingle <i>092608343-0047A</i>	ROOFING BLDG, #3 - ROOM #15 & #16	Black Fibrous Homogeneous	10% Glass	5% Quartz 60% Matrix 25% Non-fibrous (Other)	None Detected
A-47-Felt <i>092608343-0047B</i>	ROOFING BLDG, #3 - ROOM #15 & #16	Black Fibrous Homogeneous	40% Glass	40% Matrix 20% Non-fibrous (Other)	None Detected
A-48-Membrane <i>092608343-0048</i>	ROOFING BLDG, #3 - ROOM #15 & #16	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-48-Shingle <i>092608343-0048A</i>	ROOFING BLDG, #3 - ROOM #15 & #16	Black Fibrous Homogeneous	10% Glass	5% Quartz 60% Matrix 25% Non-fibrous (Other)	None Detected
A-48-Felt <i>092608343-0048B</i>	ROOFING BLDG, #3 - ROOM #15 & #16	Black Fibrous Homogeneous	40% Glass	40% Matrix 20% Non-fibrous (Other)	None Detected
A-49-Membrane <i>092608343-0049</i>	ROODING BLDG, #2 - ROOM #17 & #18	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-49-Shingle <i>092608343-0049A</i> <i>This is a composite result of inseparable roofing layers.</i>	ROODING BLDG, #2 - ROOM #17 & #18	Black Fibrous Homogeneous	15% Glass	5% Quartz 50% Matrix 30% Non-fibrous (Other)	None Detected
A-50-Membrane <i>092608343-0050</i>	ROODING BLDG, #2 - ROOM #17 & #18	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
A-50-Shingle <i>092608343-0050A</i>	ROODING BLDG, #2 - ROOM #17 & #18	Black Fibrous Homogeneous	10% Glass	5% Quartz 60% Matrix 25% Non-fibrous (Other)	None Detected
A-51-Membrane <i>092608343-0051</i>	ROOFING BLDG. #1 - ROOM #19	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected

Report amended: 08/03/2026 16:08:37 Replaces initial report from: 07/31/2026 10:56:26 Reason Code: Client-Change to Sample ID



EMSL Analytical, Inc.

464 McCormick Street San Leandro, CA 94577

Tel/Fax: (510) 895-3675 / (510) 895-3680

<http://www.EMSL.com> / sanleandrolab@emsl.com

EMSL Order: 092608343

Customer ID: 32MOUN22

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-51-Roofing	ROOFING BLDG. #1 - ROOM #19	Black Fibrous Homogeneous	20% Cellulose	30% Matrix 48% Non-fibrous (Other)	2% Chrysotile
092608343-0051A <i>This is a composite result of inseparable roofing layers.</i>					
A-51-Shingle	ROOFING BLDG. #1 - ROOM #19	Brown/Gray/Black Fibrous Homogeneous	30% Cellulose	20% Matrix 20% Non-fibrous (Other)	30% Chrysotile
092608343-0051B					
A-52-Membrane	ROOFING BLDG. #1 - ROOM #19	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0052					
A-52-Roofing	ROOFING BLDG. #1 - ROOM #19	Black Fibrous Homogeneous	20% Cellulose	30% Matrix 48% Non-fibrous (Other)	2% Chrysotile
092608343-0052A					
A-53-Membrane	ROOFING BLDG. #4 - ROOM #23	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0053					
A-53-Shingle	ROOFING BLDG. #4 - ROOM #23	Gray/Black Fibrous Homogeneous	20% Glass	50% Matrix 30% Non-fibrous (Other)	None Detected
092608343-0053A					
A-53-Felt	ROOFING BLDG. #4 - ROOM #23	Black Fibrous Homogeneous	60% Glass	20% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0053B					
A-54-Membrane	ROOFING BLDG. #4 - ROOM #23	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0054					
A-54-Shingle	ROOFING BLDG. #4 - ROOM #23	Gray/Black Fibrous Homogeneous	20% Glass	50% Matrix 30% Non-fibrous (Other)	None Detected
092608343-0054A					
A-54-Felt	ROOFING BLDG. #4 - ROOM #23	Black Fibrous Homogeneous	60% Glass	20% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0054B					
A-55-Membrane	ROOFING BLDG. #3 - ROOM #22	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0055					
A-55-Shingle	ROOFING BLDG. #3 - ROOM #22	Gray/Black Fibrous Homogeneous	20% Glass	50% Matrix 30% Non-fibrous (Other)	None Detected
092608343-0055A					
A-55-Felt	ROOFING BLDG. #3 - ROOM #22	Black Fibrous Homogeneous	60% Glass	20% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0055B					
A-56-Membrane	ROOFING BLDG. #3 - ROOM #22	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0056					
A-56-Shingle	ROOFING BLDG. #3 - ROOM #22	Gray/Black Fibrous Homogeneous	20% Glass	50% Matrix 30% Non-fibrous (Other)	None Detected
092608343-0056A					
A-56-Felt	ROOFING BLDG. #3 - ROOM #22	Black Fibrous Homogeneous	60% Glass	20% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0056B					
A-57-Membrane	ROOFING BLDG. #2 - ROOM #21	White Non-Fibrous Homogeneous		80% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0057					
A-57-Roofing	ROOFING BLDG. #2 - ROOM #21	Gray/Black Fibrous Homogeneous	50% Glass	30% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0057A <i>This is a composite result of inseparable roofing layers.</i>					

Report amended: 08/03/2026 16:08:37 Replaces initial report from: 07/31/2026 10:56:26 Reason Code: Client-Change to Sample ID



EMSL Analytical, Inc.

464 McCormick Street San Leandro, CA 94577

Tel/Fax: (510) 895-3675 / (510) 895-3680

<http://www.EMSL.com / sanleandrolab@emsl.com>

EMSL Order: 092608343

Customer ID: 32MOUN22

Customer PO:

Project ID:

Test Report: Asbestos Analysis of Bulk Materials via AHERA Method 40CFR 763 Subpart E Appendix E supplemented with EPA 600/R-93/116 using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
A-58-Membrane	ROOFING BLDG. #2 - ROOM #21	White Non-Fibrous Homogeneous		0% Matrix 100% Non-fibrous (Other)	None Detected
092608343-0058					
A-58-Roofing	ROOFING BLDG. #2 - ROOM #21	Gray/Black Fibrous Homogeneous	50% Glass	30% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0058A This is a composite result of inseparable roofing layers.					
A-59	ROOFING BLDG. #1 - ROOM #20	Gray/Black Fibrous Homogeneous	50% Glass	30% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0059 This is a composite result of inseparable roofing layers.					
A-60-Shingle	ROOFING BLDG. #1 - ROOM #20	Gray/Black Fibrous Homogeneous	20% Glass	50% Matrix 30% Non-fibrous (Other)	None Detected
092608343-0060					
A-60-Felt	ROOFING BLDG. #1 - ROOM #20	Black Fibrous Homogeneous	60% Glass	20% Matrix 20% Non-fibrous (Other)	None Detected
092608343-0060A					

Report Comment: Sample IDs updated per client request.

Analyst(s)

Brayant Rodriguez (45)

Damaris Pineda Ayala (40)


Xeena Paul (25)

Jonathan Nomura, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc San Leandro, CA NVLAP Lab Code 101048-3, WA C884

Report amended: 08/03/2026 16:08:37 Replaces initial report from: 07/31/2026 10:56:26 Reason Code: Client-Change to Sample ID



Asbestos Bulk Sampling Location

1388 Patchett Drive
Newman, CA 95360

Attachment C

Mountain View Environmental
5412 Shelly Court Salida, Ca 95368
Office (209) 545-8753 Mobile (209) 484-4395

Asbestos, Lead Based Paint & Mold
Consulting, Inspections & Supervision
Specializing in CDBG funded programs
E-mail: mountainviewenvironmental@gmail.com

BULK PAINT SAMPLING

Von Renner Elementary School
1388 Patchett Drive
Newman, CA 95360



7/22/26

Mountain View Environmental
5412 Shelly Court Salida, Ca 95368
Office (209) 545-8753 Mobile (209) 484-4395

Asbestos, Lead Based Paint & Mold
Consulting, Inspections & Supervision
Specializing in CDBG funded programs
E-mail: mountainviewenvironmental@gmail.com

BULK PAINT CHIP SAMPLING REPORT

On July 22, 2026, Kenneth C. Horrillo, a California Department of Health Services Certified Lead Inspector/Assessor, DHS #11679, at the request of Matt Vargas, Director of Maintenance & Operations, to collect bulk paint samples from painted surfaces of the Von Renner Elementary School Project located at 1388 Patchett Drive Newman, CA 95360.

The purpose of the sampling was to determine whether or not the paint chip or surface coatings on the structures that will be impacted by the demolition and relocation of Portable Classrooms of the Von Renner Elementary School, are by definition lead/based paint.

The samples were taken by Ken Horrillo following the Department of Health Services (DHS) guidelines for the collection of bulk paint samples.

The collected samples were placed under a chain-of-custody and shipped via FedEx to LA Testing, 5431 Industrial Drive Huntington Beach, CA 92649, an EPA certified laboratory for analysis by Atomic Absorption Spectrometry (AA Flame).

The definition of lead/based paint is paint or other surface coating that contains an amount of lead equal to or in excess of one milligram per square centimeter (1.0 mg/mc sq) or more than half of one percent (0.5%) by weight or greater than 5,000 ppm lead.

The results of the laboratory analysis are as follows:

P-1	Paint chip / Exterior Field Rms 15-18/ Tan	1100 ppm	Not Lead/Based Paint by definition
P-2	Paint chip / Exterior Trim Rms 15-18 / Purple	<64 ppm	Not Lead/Based Paint by definition
P-3	Paint chip / Exterior Trim Rms 21-23/ Purple	<64 ppm	Not Lead/Based Paint by definition
P-4	Paint chip / Exterior Trim Rms 21-23 / Purple	<64 ppm	Not Lead/Based Paint by definition
P-5	Paint chip / Exterior Field Rms 21-23 / Tan	< 64 ppm	Not Lead/Based Paint by definition
P-6	Paint chip / Exterior Field Rm 24 / Tan	3700 ppm	Not Lead/Based Paint by definition

Mountain View Environmental
5412 Shelly Court Salida, Ca 95368
Office (209) 545-8753 Mobile (209) 484-4395

Asbestos, Lead Based Paint & Mold
Consulting, Inspections & Supervision
Specializing in CDBG funded programs
E-mail: mountainviewenvironmental@gmail.com

EXECUTIVE SUMMARY

The laboratory analysis of samples P-1, P-2, P-3, P-4, P-5 & P-6 of surface coating was found by definition not to be lead/based paint.

CAL-OSHA has certain requirements in regard to worker protection with the presents of lead in paint or surface coating.

Because some areas that are to be impacted did have detectable levels of lead Contractors should follow Cal-OSHA regulations pertaining to worker protection standards (Title 8, CCR Section 1532.1 Lead in Construction standard and any other applicable standards) in the handling and disposal of these materials.

See attachments: A- Chain of Custody
B- Laboratory Lead in Bulk Material
C- Sampling location footprint



Ken Horrillo
CAC # 10-4691
DPH #11679
Mountain View Environmental



EMSL ANALYTICAL, INC.
TESTING LABS • PRODUCTS • TRAINING

Lead Chain of Custody

EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.
200 Route 130 North
Cinnaminson, NJ 08077

PHONE: (800) 220-3675

EMAIL: CinnaminsonLeadLab@emsl.com

GES55576

If Bill-To is the same as Report-To leave this section blank. Third-party billing requires written authorization.

Customer Information	Customer ID: 32Moun22	Billing Information	Billing ID:
	Company Name: Mountain View Environmental		Company Name:
	Contact Name: Ken Horrillo		Billing Contact:
	Street Address: 5412 Shelly Court		Street Address:
	City, State, Zip: Salida, CA, 95368 Country: US		City, State, Zip: Country:
	Phone: 209 484-4395		Phone:
	Email(s) for Report: Mountainviewenvironmental@gmail.com		Email(s) for Invoice:

Project Information	
Project Name/No: 1388 Patchett Drive, Newman	Purchase Order:
EMSL LIMS Project ID: (If applicable, EMSL will provide)	US State where samples collected: State of Connecticut (CT) must select project location: ☐ Commercial (Taxable) ☐ Residential (Non-Taxable)
Sampled By Name: Ken Horrillo	Sampled By Signature: <i>Ken Horrillo</i> No. of Samples in Shipment:

Turn-Around-Time (TAT)	
☐ 3 Hour ☐ 6 Hour ☐ 24 Hour ☐ 32 Hour ☒ 48 Hour ☐ 72 Hour ☐ 96 Hour ☐ 1 Week ☐ 2 Week	Please call ahead for large projects and/or turnaround times 6 Hours or Less. *32 Hour TAT available for select tests only; samples must be submitted by 11:30am.

MATRIX	METHOD	INSTRUMENT	REPORTING LIMIT	SELECTION
CHIPS ☐ % by wt. ☒ ppm (mg/kg) ☐ mg/cm ² *Chips reporting Limit based on a minimum 0.25g sample weight. Not appropriate for Ceramic Tiles - XRF is recommended.	SW 846-7000B	Flame Atomic Absorption	*Please select reporting on left: - 0.0064% - 64 ppm - mg/cm ² - RL is Variable	☒
	SW 846-6010D	ICP-OES	*Please select reporting on left: - 0.0004% - 4 ppm - mg/cm ² - RL is Variable	☐
AIR	NIOSH 7082	Flame Atomic Absorption	3.2 µg/filter	☐
	NIOSH 7303M	ICP-OES	1.0µ g/filter	☐
	NIOSH 7303M	ICP-MS	0.05 µg/filter	☐
WIPE ☐ ASTM ☐ NON-ASTM *If no box is checked, non-ASTM Wipe is assumed	SW 846-7000B*	Flame Atomic Absorption	8 µg/wipe	☐
	SW 846-6010D*	ICP-OES	1.0 µg/wipe	☐
TCLP	SW 846-1311 / 7000B / SM 3111B	Flame Atomic Absorption	0.32 mg/L (ppm)	☐
	SW 846-1311 / SW 846-6010D*	ICP-OES	0.1 mg/L (ppm)	☐
SPLP	SW 846-1312 / 7000B / SM 3111B	Flame Atomic Absorption	0.32 mg/L (ppm)	☐
	SW 846-1312 / SW 846-6010D*	ICP-OES	0.1 mg/L (ppm)	☐
TTLC	22 CCR App. II, 7000B	Flame Atomic Absorption	32 mg/kg (ppm)	☐
	22 CCR App. II, SW 846-6010D*	ICP-OES	2 mg/kg (ppm)	☐
STLC	22 CCR App. II, 7000B	Flame Atomic Absorption	0.32 mg/L (ppm)	☐
	22 CCR App. II, SW 846-6010D*	ICP-OES	0.1 mg/L (ppm)	☐
Soil	SW 846-7000B	Flame Atomic Absorption	32 mg/kg (ppm)	☐
	SW 846-6010D*	ICP-OES	2 mg/kg (ppm)	☐
Wastewater Unpreserved ☐ Preserved with HNO ₃ ☐ PH<2	SM 3111B / SW 846-7000B	Flame Atomic Absorption	0.32 mg/L (ppm)	☐
	EPA 200.7 / 6010D	ICP-OES	0.020 mg/L (ppm)	☐
Drinking Water Unpreserved ☐ Preserved with HNO ₃ ☐ PH<2	EPA 200.5	ICP-OES	0.003 mg/L (ppm)	☐
	EPA 200.8	ICP-MS	0.001 mg/L (ppm)	☐
TSP/SPM Filter	40 CFR Part 50	ICP-OES	12 µg/filter	☐
		ICP-MS	0.6 µg/filter	☐
Other:				

Sample Number	Sample Location	Volume / Area	Date / Time Sampled
P-1	Exterior / Field Paint / Rms 15,16,17 & 18 / Tan	Bulk	7-22-26 / 11:30 am
P-2	Exterior / Trim Paint / Rms 15, 16 17 & 18 / Purple	Bulk	7-22-26 / 11:30 am
P-3	Exterior / Trim Paint / Rms 21, 22 & 23 / Purple	Bulk	7-22-26 / 11:30 am
P-4	Exterior / Trim Paint / Rms 21, 22 & 23 / Light Purple	Bulk	7-22-26 / 11:30 am
P-5	Exterior / Field Paint / Rms 21, 22 & 23 / Tan	Bulk	7-22-26 / 11:30 am

Method of Shipment: Fedex		Sample Condition Upon Receipt:	
Relinquished by: Kenneth Horrillo	Date/Time: 7-27-26 / 3:00 pm	Received by: <i>[Signature]</i>	Date/Time: 7/28/26 8:45A
Relinquished by: <i>[Signature]</i> FX	Date/Time: 7/28/26 4:00A	Received by: Chloe TZ (CFX) 07/29/26	Date/Time: 09:35AM

Controlled Document 600-25 Lead R22 03/28/2025

*6010C Available Upon Request

☒ AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.

Page 1

Attachment A



EMSL Order Number / Lab Use Only

EMAIL: CinnaminsonLeadLab@emsl.com

GE58576

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Method of Shipment: Fedex		Sample Condition Upon Receipt:	
Relinquished by: Kenneth Horrillo	Date/Time: 7-27-26 / 3:00 pm	Received by: <i>[Signature]</i> EXP ②	Date/Time: 7/28/26 8:45A
Relinquished by: <i>[Signature]</i> FX	Date/Time: 7/29/26 4:00pm	Received by:	Date/Time:

Controlled Document COC-25 Lead R22 03/28/2025



AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.



LA Testing

5431 Industrial Drive, Huntington Beach, CA, 92649
Telephone: (714)-828-4999 Fax: (714)-828-4944
www.emsl.com

EMSL Order ID: 332655576

LIMS Reference ID: GE55576

EMSL Customer ID: 32MOUN22

Attention: Ken Horrillo

Mountain View Environmental [32MOUN22]
5412 Shelly Court
Salida, CA 95368
(209) 545-8753
mountainviewenvironmental@gmail.com

Project Name: 1388 PATCHETT DRIVE, NEWMAN

Customer PO:

EMSL Sales Rep: Callum McMillan

Received: 07/29/2026 09:35

Reported: 07/31/2026 09:51

Analytical Results

Analyte	Results	RL	Weight	Prep Date & Tech	Prep Method	Analysis Date & Analyst	Analytical Method	Q	DF
Client Sample ID: P-1/EXTERIOR / FIELD PAINT / RMS 15, 16, 17 & 18 / TAN						Date Sampled: 07/22/26			
Matrix: Chips						LIMS Reference ID: GE55576-01			
Lead	1100 ppm	64 ppm	0.2583 g	07/31/26 DA1	SW-846 3050B	07/31/26 DCM	SW 846-7000B	1	
Client Sample ID: P-2/EXTERIOR / TRIM PAINT / RMS 15, 16, 17 & 18 / PURPLE						Date Sampled: 07/22/26			
Matrix: Chips						LIMS Reference ID: GE55576-02			
Lead	<64 ppm	64 ppm	0.2985 g	07/31/26 DA1	SW-846 3050B	07/31/26 DCM	SW 846-7000B	1	
Client Sample ID: P-3/EXTERIOR / TRIM PAINT / RMS 21, 22 & 23 / PURPLE						Date Sampled: 07/22/26			
Matrix: Chips						LIMS Reference ID: GE55576-03			
Lead	<64 ppm	64 ppm	0.2722 g	07/31/26 DA1	SW-846 3050B	07/31/26 DCM	SW 846-7000B	1	
Client Sample ID: P-4/EXTERIOR / TRIM PAINT / RMS 15, 16, 17 & 18 / LIGHT PURPLE						Date Sampled: 07/22/26			
Matrix: Chips						LIMS Reference ID: GE55576-04			
Lead	<64 ppm	64 ppm	0.2533 g	07/31/26 DA1	SW-846 3050B	07/31/26 DCM	SW 846-7000B	1	
Client Sample ID: P-5/EXTERIOR / FIELD PAINT / RMS 21, 22 & 23 / TAN						Date Sampled: 07/22/26			
Matrix: Chips						LIMS Reference ID: GE55576-05			
Lead	<64 ppm	64 ppm	0.2765 g	07/31/26 DA1	SW-846 3050B	07/31/26 DCM	SW 846-7000B	1	
Client Sample ID: P-6/EXTERIOR / FIELD PAINT / RM. 24 / TAN/ GREY						Date Sampled: 07/22/26			
Matrix: Chips						LIMS Reference ID: GE55576-06			
Lead	3700 ppm	64 ppm	0.2606 g	07/31/26 DA1	SW-846 3050B	07/31/26 DCM	SW 846-7000B	1	



LA Testing

5431 Industrial Drive, Huntington Beach, CA, 92649
Telephone: (714)-828-4999 Fax: (714)-828-4944
www.emsl.com

EMSL Order ID: 332655576

LIMS Reference ID: GE55576

EMSL Customer ID: 32MOUN22

Attention: Ken Horrillo

Mountain View Environmental [32MOUN22]
5412 Shelly Court
Salida, CA 95368
(209) 545-8753
mountainviewenvironmental@gmail.com

Project Name: 1388 PATCHETT DRIVE, NEWMAN

Customer PO:

EMSL Sales Rep: Callum McMillan

Received: 07/29/2026 09:35

Reported: 07/31/2026 09:51

Certified Analyses included in this Report

Analyte	Certifications
SW 846-7000B in Chips	
Lead	33-AIHA ELLAP

List of Certifications

Code	Description	Number	Expires
33-AIHA ELLAP	American Industrial Hygiene Association (AIHA LAP, LLC) - ELLAP	101650	02/01/2027
33-AIHA IHLAP	American Industrial Hygiene Association (AIHA LAP, LLC) - IHLAP	101650	02/01/2027
33-CA Water Boards	California Water Boards	1406	01/31/2028

Please see the specific Field of Testing (FOT) on www.emsl.com <<http://www.emsl.com>> for a complete listing of parameters for which EMSL is certified.

Notes and Definitions

Item	Definition
(Dig)	For metals analysis, sample was digested.
[2C]	Reported from the second channel in dual column analysis.
DA	Direct Analysis
DF	Dilution Factor
MDL	Method Detection Limit.
ND	Analyte was NOT DETECTED at or above the reporting limit, or the mdl if provided.
NR	Spike/Surrogate showed no recovery.
Q	Qualifier
RCS	Respirable Crystalline Silica
RL	Reporting Limit
Wet	Sample is not dry weight corrected.

Measurement of uncertainty and any applicable definitions of method modifications are available upon request. Per EPA NLLAP policy, sample results are not blank corrected.



LA Testing

5431 Industrial Drive, Huntington Beach, CA, 92649
Telephone: (714)-828-4999 Fax: (714)-828-4944
www.emsl.com

EMSL Order ID: 332655576

LIMS Reference ID: GE55576

EMSL Customer ID: 32MOUN22

Attention: Ken Horrillo

Mountain View Environmental [32MOUN22]
5412 Shelly Court
Salida, CA 95368
(209) 545-8753
mountainviewenvironmental@gmail.com

Project Name: 1388 PATCHETT DRIVE, NEWMAN

Customer PO:

EMSL Sales Rep: Callum McMillan


Received: 07/29/2026 09:35

Reported: 07/31/2026 09:51

Michael Chapman Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. QC sample results are within quality control criteria and met method specifications unless otherwise noted. All results for soil samples are reported on a dry weight basis, unless otherwise noted.

Analysis following EMSL SOP for the Determination of Environmental Lead by FLAA. The laboratory has a reporting limit of 0.0064% by wt., based upon a minimum sample weight of 0.25g submitted to the lab, and is not responsible for any result or reporting limit provided in mg/cm² since it is dependent upon an area value provided by non-lab personnel. A "<" (less than) result signifies that the analyte was not detected at or above the reporting limit. Measurement of uncertainty and definitions of modifications are available upon request. Results in this report are not blank corrected unless specified.



lead Based Paint Bulk Sampling Location

1388 Patchett Drive
Newman, CA 95360

Attachment C