

|                                      |   |   |  |
|--------------------------------------|---|---|--|
| <b>PROJECT NAME:</b>                 |   | <b>FILLMORE HIGH SCHOOL<br/>NEW ATHLETIC COMPLEX</b>    |  |
| <b>PROJECT NUMBER:</b>               |   | <b>Project No. 2024-017 / DSA #03-123950</b>            |  |
| <b>TO:</b>                           |   | <b>RJ Stump</b><br><b>Fillmore Unified School Dist.</b> | <b>EMAIL:</b> <a href="mailto:rj.stump@fillmoreusd.org">rj.stump@fillmoreusd.org</a> |
|                                      |   | <b>Roy Frey</b><br><b>WestGroup Designs</b>             | <a href="mailto:royf@westgroupdesigns.com">royf@westgroupdesigns.com</a>             |
| <b>DATE:</b>                         | <b>February 3, 2025</b>   |   |  |
| <b>FROM:</b>                         | <b>Icon West, Inc.</b><br><b>520 S. La Fayette Park Pl, Suite 503</b><br><b>Los Angeles, CA 90057</b> | <b>EMAIL:</b>   | <b>felix@icon-west.com</b>   |
| <b>DOCUMENT/DIVISION<br/>NUMBER:</b> |   | <b>Alt #1 - Roof Repair Specs</b>                       | <b>DRAWING<br/>NUMBER:</b>   |

Please provide Roof Repair Specs for Bldg #12, Gym Lockers, with information of type of roofing, required walkpads and warranty, for the required roof patch at the HVAC Units.

Roy Frey - Westgroup Designs - 01/29/2025