



5/30/2025

**Client** Willdan  
**Address** Willdan  
374 Poli Street, Suite 101  
Ventura CA, 93031

## Durability Index

Caltrans CT229

**Date Tested** 10/4/2024  
**Sample Rec. Date** 10/20/2024  
**Date Sampled** 9/20/2024  
**Sampled By** Client  
**Sample Id** 3K7

### Client Reference No

**Project No** 0551

**Project** Willdan - Ridgecrest, Pinny Pool Demo

### Material Source

**Material Description** Silty-Sand(SM); yellowish brown, moist

**Location Detail** PROJECT: 205 S Warner St, Ridgecrest, CA 93555 DETAIL: Sampled onsite

---

<b>Fine Durability Index (Df)</b>	71
<b>Coarse Durability Index (Dc)</b>	
<b>Durability Index</b>	71

---

### Remarks

**Technician** Job Sanchez  
Digital Signature By User Login

**Manager** Evan Folk  
Digital Signature By User Login

Test results relate only to the sample tested. This test report shall not reproduced, except in full, without the prior written approval of the agency.

**Lab Address** 2247 Statham Blvd. Oxnard CA, 93033

**System Link** <http://umt.vahalo.com/assignments/5C10BBA6-C442-4207-591B-61778C56135A>

**System Path** Willdan - Ridgecrest, Pinny Pool Demo / Subgrade & Base Density Testing / 0551 Fine Durability Index 240920

5/30/2025 3:46:53 PM

1/1